


Procedure for updating the XU208 USB transceiver's firmware and PID


The XU208 flash memory is initially programmed with firmware version 6.6C which uses standard XMOS identification codes (PID 0x0008).

Updating to Firmware version 6.F2 brings several improvements (stability, high-res formats support) and switch to Engineered custom identification code (PID 0x3076).


1. On a windows-based computer, install the following driver:
XMOS_TUSBAudio_eval_v4.11.0_2017-05-16_setup
2. Once driver installation is finished, check the XMOS firmware version with the deriver control panel




3. Launch the DFU application located into:
Program Files / Thesycon / TUSBAudio_Driver/W10x64



4. Select the binary file for update and click Start



5. Once the update is finished, unplug the device and install the new driver:
XMOS-Stereo-USB-Audio-Class2-Driver-3076_v4.13.0.exe



6. The computer may need to be restarted for the driver to recognize the device. Final check with the new driver control panel:

